

Connectors lay out centipede 100:


Byte4 bit 76543210 Byte3 bit 76543210 Byte2 bit 76543210 Byte1 bit 76543210

Byte5
Bit 7-0

Byte6
Bit 7-0

Byte7
Bit 7-0

Byte8
Bit 7-0



P1.0	Baud rate control:	
P1.1	Baud	P1.0 P1.1
P1.2	2400	0 0
P1.3	4800	0 1
P1.4	9600	1 0
P1.5	19200	1 1
P1.6		
P1.7	Data Format	P1.2
RST	Send ASCII	0
	Send HEX	1

Relay o/p bit 0123

Byte9 bit 01234567

Byte10 bit 01234567

o/p1 bit 01234567

o/p2 bit 01234567